

Replacement Sheet




FIG. 2A






FIG. 2B





Replacement Sheet

FIG. 2C






FIG. 2D



FIG. 2E



128





Replacement Sheet

FIG. 2F




FIG. 2G






FIG. 2H



Replacement Sheet





Replacement Sheet

FIG. 6C







FIG. 6D



Replacement Sheet





Replacement Sheet

FIG. 8A





FIG. 8B



Replacement Sheet





FIG. 9A




FIG. 9B



Replacement Sheet




FIG. 10A




FIG. 10B

Replacement Sheet




FIG. 10C




FIG. 10D





FIG. 10E



Replacement Sheet




FIG. 11A




FIG. 11B

Replacement Sheet





FIG. 12A




FIG. 12B




FIG. 13A





FIG. 13B



Replacement Sheet

FIG. 14A






FIG. 14B





Annotated Sheet Showing Changes




FIG. 2A

Straighten lead line








FIG. 2B



Annotated Sheet Showing Changes





Annotated Sheet Showing Changes

FIG. 2F




FIG. 2G








FIG. 2H









Annotated Sheet Showing Changes






Annotated Sheet Showing Changes





Annotated Sheet Showing Changes





Annotated Sheet Showing Changes




FIG. 8A





FIG. 8B



Annotated Sheet Showing Changes




FIG. 9A




FIG. 9B




FIG. 10A








FIG. 10B





Annotated Sheet Showing Changes




FIG. 11A






FIG. 11B







FIG. 13A




FIG. 13B

Show metal base 120



Annotated Sheet Showing Changes




FIG. 14A




FIG. 14B

Show metal base 120